

Norton Model 50, Slimline frame, 1961 engine sprocket details.



Figure one. Engine sprocket, crankcase side view, 17 teeth.




Figure two. Engine sprocket, top view, 17 teeth; *center line* of chain path appears to be ~ 1" in from the crank case side and ~1/4" from primary case / alternator rotor.